

Heavy Equipment

Inspection Date Nov 10, 2018 11:05 am CST

Job # NA 1128 1178

Ordered Nov 8, 2018 1:49 pm CST

Delivered Nov 10, 2018 11:41 am CST

Country US



Order Information

Asset ID

Not Provided

Location

1708 U.S. 9

Wappingers Falls, NY 12590

Equipment Details

VIN (Driver Side Door)

1FUJA6CK3ADAT9995

Year

2010

Make

Freightliner

Model

Columbia

Mileage

586171

Videos

Heavy Equipment


Inspection Date Nov 10, 2018 11:05 am CST

Job # NA 1128 1178

Ordered Nov 8, 2018 1:49 pm CST

Delivered Nov 10, 2018 11:41 am CST

Country US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards

Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Heavy Equipment

Inspection Date Nov 10, 2018 11:05 am CST

Job # NA 1128 1178

Ordered Nov 8, 2018 1:49 pm CST

Delivered Nov 10, 2018 11:41 am CST

Country US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

Media - Interior Condition Photos

Heavy Equipment


Inspection Date Nov 10, 2018 11:05 am CST

Job # NA 1128 1178

Ordered Nov 8, 2018 1:49 pm CST

Delivered Nov 10, 2018 11:41 am CST

Country US



Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)



Passenger Side Interior Full View

Operating Condition

What is the condition of the Interior?

Good

Are there any tears in the upholstery?

No

Heavy Equipment

Inspection Date Nov 10, 2018 11:05 am CST

Job # NA 1128 1178

Ordered Nov 8, 2018 1:49 pm CST

Delivered Nov 10, 2018 11:41 am CST

Country US



Are there any strange odors in the vehicle? If so, provide a short description

No

Is there any missing equipment (ie lights etc)? If so, provide details

None observed
