Inspection Date May 20, 2022 10:32 am CDT Job # NA 8317 7837 Ordered May 18, 2022 10:11 pm CDT Delivered May 21, 2022 10:42 am CDT Country US



Order Information
Asset ID
not provided
.ocation 000 Prince Georges Boulevard Jpper Marlboro, MD 20774
Equipment Details
/IN (Driver Side Door)
DW1A5320DB380344
'ear
2013
Make
TOUGHTON TRAILERS
TOUGHTON TRAILERS
Model
itoughton trailers
Mileage


Videos

Inspection Date May 20, 2022 10:32 am CDT Job # NA 8317 7837 Ordered May 18, 2022 10:11 pm CDT Delivered May 21, 2022 10:42 am CDT Country US





Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards

Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Inspection Date May 20, 2022 10:32 am CDT Job # NA 8317 7837 Ordered May 18, 2022 10:11 pm CDT Delivered May 21, 2022 10:42 am CDT Country US









Driver Side Full View

Rear Full View

Passenger Side Full View



Passenger Side Front Corner Full View

Media - Exterior Damage Photos

Inspection Date May 20, 2022 10:32 am CDT Job # NA 8317 7837 Ordered May 18, 2022 10:11 pm CDT Delivered May 21, 2022 10:42 am CDT Country US









No clue No clue No clue

Media - Interior Condition Photos



Driver Side Interior Full View



Dashboard Full View (key on if available)




Odometer/Hours Reading (key on if required/available)

Inspection Date May 20, 2022 10:32 am CDT Job # NA 8317 7837 Ordered May 18, 2022 10:11 pm CDT Delivered May 21, 2022 10:42 am CDT Country US





Sleeper Cab/Rear Interior 1 (if applicable)



Sleeper Cab/Rear Interior 2 (if applicable)



Passenger Side Interior Full View

Operating Condition

What is the condition of the Interior?

Fair

Are there any tears in the upholstery?

No

Are there any strange odors in the vehicle? If so, provide a short description

N/A

Is there any missing equipment (ie lights etc)? If so, provide details

N/A