Heavy Equipment Inspection Date May 20, 2022 10:32 am CDT Job # NA 5289 8962 Ordered May 18, 2022 10:15 pm CDT Delivered May 21, 2022 10:47 am CDT Country US



Order Information

Asset ID

not provided

Location

1000 Prince Georges Boulevard Upper Marlboro, MD 20774

Equipment Details

VIN (Driver Side Door)

1DW1A5325CB326746

Year

2012

Make

STOUGHTON TRAILERS

Model

Stoughton trailers


Mileage

123456

Videos

Inspection Date May 20, 2022 10:32 am CDT Job # NA 5289 8962 Ordered May 18, 2022 10:15 pm CDT Delivered May 21, 2022 10:47 am CDT Country US





Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards

Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Inspection Date May 20, 2022 10:32 am CDT Job # NA 5289 8962 Ordered May 18, 2022 10:15 pm CDT Delivered May 21, 2022 10:47 am CDT Country US





Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

Media - Exterior Damage Photos

Inspection Date May 20, 2022 10:32 am CDT Job # NA 5289 8962 Ordered May 18, 2022 10:15 pm CDT Delivered May 21, 2022 10:47 am CDT Country US





No clu e



No clue



No clue



No clue

Media - Interior Condition Photos

Inspection Date May 20, 2022 10:32 am CDT Job # NA 5289 8962 Ordered May 18, 2022 10:15 pm CDT Delivered May 21, 2022 10:47 am CDT Country US





Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)



Sleeper Cab/Rear Interior 1 (if applicable)



Sleeper Cab/Rear Interior 2 (if applicable)



Passenger Side Interior Full View

Operating Condition

What is the condition of the Interior? Good

Are there any tears in the upholstery?

No

Heavy Equipment Inspection Date May 20, 2022 10:32 am CDT Job # NA 5289 8962 Ordered May 18, 2022 10:15 pm CDT Delivered May 21, 2022 10:47 am CDT Country US



Are there any strange odors in the vehicle? If so, provide a short description N/A

Is there any missing equipment (ie lights etc)? If so, provide details

N/A